PLANNED TO SIMULATE ARTICLE PATTERNS AND CHARACTERISTICS.

ACCIDENT OCCURRED ON INITIAL T/O. FUEL LOAD WAS 650 GALLONS.

ALL GROUND AND FLIGHT INDICATIONS WERE NORMAL UP TO IMMEDIATELY

AFTER BECOMING AIRBORNE. AIRCRAFT WAS AT 115 KTS APPROXIMATELY

PILOT.

25X1A

25X1A

25X1A

FILE INFO		(When Fill	l l		
		REPRODUCTION	PROHIBITED		
ACTION	1	6	11	16	
AOTION	2	7	12	17	
	3	8	13	18	
A	4	9	14	19	
	5	1ø	15	2ø	
PAGE 2		CRET			

2000 FT RUNWAY REMAINING. AT THIS TIME BOTH PILOTS NOTICED A/S DROP TO 110 AND FELT DECREASE IN POWER. THROTTLE WAS RECHECKED OPEN.

GANGSTART WAS NOT ACTIVATED, TIP TANKS WERE RETAINED.

AIRCRAFT BRIEFLY CONTACTED THE RUNWAY TWICE IN THE REMAINING 2000 FEET. SUBSEQUENT GROUND CONTACT WAS APPROX 228 YARDS FROM THE

- END OF THE OVERRUN AND THE AIRCRAFT CAME TO REST APPROX 700 YARDS FROM THE END OF THE OVERRUN. THE CREW CONTROL PERFORMED EMERGENCY SHUT-DOWN PROCEDURES AND EVACUATED THE AIRCRAFT. CANOPY WAS NOT

- JETTISONED.

13 UNEXPLAINED LOS OF POWER DURING T/O

16. A. PENDING

B. HELD AT

C. N/A

D. N/A

E. N/A

F. FORMAL RELEASE NOT MADE. FACT THAT A T-33 CRASHED AT EDWARDS, NO INJURY, WILL BE RELEASED BY EDWARDS AFB INFORMATION OFFICER IF PRESSED.

G. TO FOLLOW AS APPROPRIATE.

SECRET

BT

25X1A